



## INFO

---

This document provides a brief overview of the changes introduced in NightWatch v16.0 compared to v15.5. The seizure detection algorithms and API functionality remain unchanged.

- Basestation software version: v16.0
- Arm module software version: Build number 160

## CHANGES

---

1. Minor fix for the hardware-error alarm that verifies the accelerometer's functionality. In v15.5, this alarm could trigger rarely when the accelerometer was actually not defective.
2. Minor fix for the arm module to address rare pairing issues with the basestation.
3. Added an automatic log-out period (10 minutes) for the basestation's web interface.
4. Added a log-out button to the basestation's web interface
5. Added a 'DNS-server' to the settings of the basestation's web interface.
6. Improvement of internet LED behavior.